

E40 REFURBISHMENT 2026

8/6/2026

1. Cost of all the graphics and striping installed by Jerry Williams \$ 3,350.00
2. Cost of Dave Clark headsets Installed. \$ 9,420.80
3. Cost of BK KNGM150 Dash mounted radio installed. \$ 3,625.72
- 3a. Cost of 4 new BK5000 portable radios \$ 8,784.18
4. Item #4 water tank leak. Being repaired this week.
5. Item #5 radiator tank leak and chemical analysis of antifreeze. Replaced water pump and replaced leaking front main seal. This job is complete.
6. Item #22 Aux pump leaking oil. The leak has been resolved but after further inspection of the engine have found the thermostat housing to be badly corroded and in need of repair.
7. **LED LIGHTING; The estimated cost of new Whelen lighting stands at \$ 19,500.00. The, 2 biggest cost items are the brow light bar at \$ 4,000.00 and the LED light bar at \$ 8,000.00. Still waiting on price for cost labor to install. Have give permission to Riverview to order the lighting package because it could take several months to ship.**
\$ 19,500.00
8. **PAINTING; Riverview has asked for and received two bids to paint E40. Both bids came in around \$ 40,000.00 to paint E40. The plan is to visit both paint shops and determine which shop is capable of doing the quality of work we are asking for.**
\$ 40,000.00
9. A request for the price of the Rollup doors has been made. A rough estimate for the price of the doors is around \$14,000.00. One added bonus to buying new doors is they come with LED lighting strips already installed in the frame rails. As soon as Riverview gets a firm quote on the price of the rollup doors, we should plan to order them because it could take 3 to 4 months to receive them.
\$ 14,000.00
10. More research needed to find a backup camera that can be adapted to E40.

The initial cost of repairs requested 6/1/2026 was

\$ 72,791.63